

INSTRUCTION MANUAL

WG - 11

FACE GUARD

READ FOLLOWING INSTRUCTIONS THOROUGHLY BEFORE ATTEMPTING TO USE.

KEEP THIS MANUAL ALWAYS IN THE VICINITY OF USE FOR YOUR REFERENCE.

BEFORE USING THE UNIT, CHECK IF THERE ARE ANY DAMAGES ON THE UNIT

DUE TO TRANSPORT CONDITIONS. IF ANY DAMAGES ARE FOUND, CONTACT YOUR

NEAREST DEALER.

CAUTION (INDICATES THAT INCORRECT OPERATION PRESENTS POSSIBILITY OF INJURY TO THE USER OR DAMAGE TO THE UNIT.)

- 1. DO NOT TAKE OFF FACESHIELD NOR LIFT UP THE VISOR WHEN WORKING.
- 2. DO NOT USE THIS EYE PROTECTION WHERE ENVIRONMENTAL TEMPARATURE IS HOT. IT HAS NO HEAT-RESISTANT.
- 3. DO NOT DISASSEMBLE AND REMODEL THE PRODUCT.
- 4. USE BOTH THE FACE GARD (WG-11 OF OUR MINIMO PRODUCT) AND AN EYE PROTECTION IN THE CIRCUMSTANCE WHERE CHEMICAL LIQUID OR CHEMICAL POWDER MAY SPRAY FLYING THROUGH THE AIR. USING ONLY A FACESHIELD IS NOT GOOD ENOUGH FOR YOUR SAFETY UNDER LIQUIDS SPLASH CIRCUMSTANCE.
- 5. CHECK IF ANY SCRATCHES OF THE SURFACE, DEFECTS, DEFORMATIONS OR DIRTY VISOR BEFORE USING IT FOR YOUR SAFETY. THEY REDUCE YOUR VISION.

1. FEATURES

- PROVIDE PROTECTION FROM MINOR IMPACTS, SPARKS, LIQUIDS AND MOLTEN METAL SPLASHES.
- ■HELPS PROVIDE ADDITIONAL PROTECTION OF THE FACE AND EYES WHEN PROTECTIVE EYEWEAR SUCH AS WG-03 OF OUR MINIMO PRODUCTS IS BEING WORN.
- THE MATERIALS:

VISOR: ACRYLIC GIVES CLEAR VISION AND GOOD AGAINST CHEMICALS

FRAME: POLYCARBONATE HEAT RESISTING MATERIAL

(DEFORMATION TEMPARATURE IS 130 ~ 138°C)

■ANTI-FOG TREATMENT IS DONE

2. INSTALL

■ WEARING

SET IT ON YOUR HEAD AND FASTEN UPPER HOOK-AND-LOOP FASTENER AND ALSO FASTEN BACK HOOK-AND-LOOP FASTENER TO FIT YOUR HEAD.

TO TAKE IT OFF, SIMPLY UNFASTEN TWO FASTENERS.

3. MAINTENANCE

Safety eyewear should be inspected frequently. Scratched and dirty lenses reduce vision, cause glares and lose their impact resistance. If the frames on your protective eyewear are broken and bent, chances are, your eyewear doesn't fit properly and may contribute to accidents. Designed to protect from accidental injury, safety eyewear will not withstand repeated impact or abuse.

- 1) PLEASE DO NOT DAMAGE THE PROTECTION SIDE.
- (2)DO NOT WIPE THE VISOR WITH DIRTY TOWEL, DIRTY CLOTH OR GLOVES.
- ③WHEN IT GETS DIRT BY OIL OR DUST, SOAK THE VISOR INTO THE DILUTED DETERGENT, THEN WIPE IT WITH SOFT CLOTH.
- (4)STORE THE FACEGUARD IN A PLASTIC BAG WHEN NOT BEING USED TO PREVENT SCRATCHING.
- ⑤ INSPECT THE FACEGUARD REGULARLY FOR DAMAGE OR DEFECT, AND REPLACE WHEN NECESSARY.
- ©REPLACE VISOR THAT ARE SCRATCHED, PITTED, BENT, OR HAVE AN OUTDATED PRESCRIPTION.
- THE SCREW MIGHT LOOSEN WHEN USING IT FOR A LONG TIME. PLEASE CHECK AT EACH USE.
- (8)KEEP THE VISION CLEAR BY CLEANING THE VISOR AFTER EACH WORK SHIFT.

MINITOR CO., LTD. JAPAN

21-1 Ryogoku 3-chome, Sumida-ku, Tokyo 130-0026 JAPAN Phone +81 3 (6630) 5800 FAX +81 3 (6630) 5795